

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SA02536AK

This Certificate issued to Airframes Alaska
81 Commercial Drive
Palmer, AK 99645

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product Type Certificate Number: 1A2

Make: Piper

Model: PA-18, PA-18S, PA-18 "105" (Special), PA-18S "105" (Special), PA-18A, PA-18 "125" (Army L-21A), PA-18S "125", PA-18AS "125", PA-18 "135" (Army L-21B), PA-18A "135", PA-18S "135", PA-18AS "135", PA-18 "150", PA-18A "150", PA-18S "150", PA-18AS "150", PA-19 (Army L-18C), PA-19S

Description of Type Design Change:

Installation of Airframes Alaska Piper PA-18 Light Weight Landing Gear Safety Ropes in accordance with Airframes Alaska Light Weight PA-18 Landing Gear Safety Rope MDL, Revision A, dated April 14, 2020, or later FAA approved revision.

Limitations and Conditions:

1. This approval is limited to aircraft models listed that have three inch extended main landing gear installed.
2. The compatibility of this design change with previously approved modifications must be determined by the installer.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.
4. The FAA has determined that no Instructions for Continued Airworthiness are required for this STC.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 24, 2019

Date reissued:

Date of issuance: April 14, 2020

Date amended:



By direction of the Administrator:

(Signature)

August A. Asay
Manager, Anchorage ACO Branch

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.